## LIST OF FOG9 & SOG5 CHANGES - 100CT2021

## Both FOG @ SOG

- Sect 0 Change to FOG9 and SOG 5 with Oct 2021 Date Foreword includes updated contact email
- Sect 1 No Change to either
- Sect 2 Change to Both on Pg2-57: Add to upper graphic "(6x Header & Sole width is needed for full bearing)"
- Sect 3 Change to show sloping Bottom Brace (previously shown level) On Pages 3-2, 3-20, & 3-25
- Sect 4 Pg. 4-22, Clarifying remarks to last paragraph of "Ans. LP-1"

Pg. 4-25, Clarifications added

Pg. 4-26, Ans. R-1 updated

Pg. 4-29, Q&A "L-1" updated for clarity

## FOG9 ONLY

Sect 5 – Pg. 5-2, US&R Field Documentation (Survey123)

Pg. 5-3, additional GPS/Computer interface Bullet

- Various clarifying edits and content relative to newer garmin GPS devices added (note: 60CSx content remains but will likely be removed from future FOG versions)
- Garmin "MapSource" references have been replaced with "Basecamp" and "Garmin Express"
- Pg. 5-10, Track Log intervals description updated
- Pg. 5-13, Garmin 64 model references added to this section
- Pg. 5-30, Garmin Software section has been updated for "Basecamp" (replacing "MapSource")
- Pg. 5-44, Nikon Total Station Models applicable to these instructions
- Sect 6 Pg 6-3, Change RST nomenclature for Probability of having Viable Victims to:

Potential number trapped – HIGH MEDIUM LOW

Victim access effort - EASY MEDIUM DIFFICULT

Type of voids - OPEN SEPARATED COMPACT

Pg 6-6, Replace RST-1 Form with new version

Pg 6-8, "PG1" of the I-880 Emergency Shoring Graphic has been restored (previously missing from Edition 8)

Sect 7 - No Change

Sect 8 – Page 8-6: Up-date Regional Equipment Cache per Jeff

Sect 9 - Forms have been updated

Page 9-11 MIT-1 Form description updated

SHOR-1 Form was fixed to correct typo in upper left quad "Potential" Victim Location Last Bullet: Avoid, "Remove", Limit Access